

Stantec Consulting Service Inc.
5 LAN Drive, Suite 300
Westford MA U.S.A.
01886
Tel. 978.692.1913
Fax. 978.692.4578
www.stantec.com

Stantec

Copyright Reserved

The Contractor shall verify and be responsible for all dimensions.
DO NOT scale the drawing - and errors or omissions shall be
reported to Stantec without delay.
The Copyrights to all design and drawings are the property of
Stantec. Reproduction or use for any purpose other than that
authorized by Stantec is forbidden.

Consultants

Legend


Notes

Revision By Appd. YY.MM.DD

Issued By Appd. YY.MM.DD

File Name: DDD COL DDD Nov. '09
Dwn. Chkd. Dsgn. YY.MM.DD

Permit-Seal



Client/Project
CITY OF NEWTON

WABAN HILL RESERVOIR IMPROVEMENTS
"CONTRACT 2"
Newton, Massachusetts

Title
Waban Hill Reservoir Improvements
Architectural Roof Plans

Project No. 195112116 Scale As Shown


Drawing No. Sheet Revision

A-1

1 of 2

Typical Demolition Notes:



- 1 Remove all existing asphalt shingle roofing and any sub-roofing material to the plywood decking, typ. at all roof areas.
- 2 Inspect all plywood roof decking and replace any damaged or rotted areas typically; Review with engineer prior to replacing any decking areas.
- 3 Remove all existing dome skylights and infill with new wood framing and new plywood decking to match existing installations typ.
- 4 Existing "camera" elements to remain; Protect as required for demolition work and new installations typ.



Waban Hill Reservoir DEMOLITION Roof Plan

2
A1

Scale = 1/4" = 1'-0"



Waban Hill Reservoir Existing Condition Roof Plan

1
A1

Scale = 1/4" = 1'-0"

